


## 07-CUR. SPRINTER VAN DRILLING INTO THE BODY IS REQUIRED

IN354 7/21/08


INSTALLATION S PARTS LIST:  ADDITIONAL PARTS MAY BE INCLUDED AND MAY NOT BE USED ON ALL APPLICATIONS.		
N _ w w	8	917. 2 4
1/4x5/8" SQUARE HEAD SCREW 1/4-20 HEX NUT FL139D AS11	3/8"x1 SELF TAPPING SCREW #14x3/4" TEK SCREW	<u>DESCRIPTION</u> RUNNING BOARD 1 DRIVER & 1 PASSENGER END CAP, 2 LEFT & 2 RIGHT
4 _	16 2	QIY. 4 16
BENT TAB BT52, W/HOLE FL139P	5/16-18 HEX WASHER HEAD NUT FLAT BRACKET, FL124	DESCRIPTION HORIZONTAL BRACKET, SUPPORT, 3124F 5/16"x 3/4" BOLT

TOOLS REQUIRED: 5/16" DRILL \* 1/2" HEX SOCKET \* 1/2" WRENCH \* 5/16" NUT DRIVER \* 3/8" NUT DRIVER



(2)


BRACKET ASSEMBLY ASSEMBLE WITH 5/16" BOLTS





FORWARD ASSEMBLY MOUNT TO BODY


PREDRILL A 5/16" HOLE THROUGH THE PINCH WELD. ATTACH FL124 BRACKET (A) TO THE BODY WITH 5/16" BOLT AND NUT, LOOSLY TIGHTEN. ATTACH THE BT52 BENT TAB TO THE BODY PANEL WITH A #14x 3/4" SELF DRILLING SCREW. ONLY DRILL INTO THE FLOOR UNDER THE FRONT DOORS. ATTACH AS11 TO FRONT BRACKETS ONLY WITH 5/16" BOLT & NUT. ATTACH OTHER END TO BODY BEHIND THE FRONT WHEEL WITH #14 X 3/4" SELF DRILLING SCREW.





## SECOND BRACKET MOUNTING

PREDRILL A 5/16" HOLE THROUGH THE PINCH WELD. ATTACH FL139D BRACKET TO THE BODY WITH 5/16" BOLT AND NUT, LOOSLY TIGHTEN. ATTACH THE TOP TO THE CROSS BRACE WITH #14 X 3/4" SELF DRILLING SCREWS.




MOUNT AT LOCATIONS SHOWN AT

(B)




## (EXTRUDED & DIAMOND BOARDS ONLY)

FASTEN END CAP TO BOARDS WITH 3/8" SELF TAPPING BOLT. INSTALL END CAP TO OTHER END OF BOARD



BOARDS WITH WELDED END CAPS WILL ONLY NEED TO SLIDE IN THE BOLTS INTO THE TRACK IN THIS STEP.



WITH BOARD LEVEL TIGHTEN ALL LOOSE BOLTS

IN354

REPEAT FOR OTHER SIDE

PAGE 3